

(B) @SimplyPlumbing | YaletownPlumbing



HST #837181627

DATE 2018-09-28	TECHNICIAN Darren Mann		JOB/ORDER # 8897		REFERENCE TEXT Client reference				
FIRST NAME David		LAST NAME Yang							
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA		4	SERVICE ADDRESS 3103 - 33 SMITHE MEWS SUITE VACANT, KEYS AVAILABLE FOR PICKUP. VANCOUVER, BRITISH COLUMBIA, CANADA						
PHONE 778.988.8470				EMAIL PMVan1@rentitfurnished.com					

REASON FOR TODAY'S CALL: garburator jammed.

DESCRIPTION OF WORK PERFORMED:

The garburator was completely seized up and there were cracks in the housing. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION			PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator			\$279.00
<i>Q.</i>	(1	warranty:	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		\$279.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Thank Youl			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$13.95
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$292.95
		ve did. MADE THAT S MATERIALS L	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK		

CUSTOMER SIGNATURE

DATE