

HST #837181627

DATE 2018-10-09	TECHNICIAN Darren Mann		JOB/ORDER # 8916		REFERENCE TEXT Client reference
FIRST NAME David		LAST NAME Hung			
BILLING ADDRESS COMPANY / BILLING NAME 702 - 1495 RICHARDS ST VANCOUVER, V6B6R6 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 702 - 1495 RICHARDS ST, BUZ VANCOUVER, V6B6R6 BRITISH COLUMBIA, CANADA	
PHONE 778.989.0575				EMAIL davidhung9@gmail.com	

REASON FOR TODAY'S CALL: Master bath tub drain is slow.

DESCRIPTION OF WORK PERFORMED:

-I used the PowerSpin drain snake to clean the master bathroom tub drain. Hair and half a dozen razor caps were removed. Tested by filling the tub 8? and draining. I also cleared a large clump of hair from the lavatory sink drain in the same bathroom and tested by filling and draining the sink multiple times.

QTY .	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1	Clean drain using PowerSpin / Tub/Shower					\$139.00	\$139.00
0	Rung Goodlad			PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTE MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT M		SUBTOTAL:	\$139.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		·			GST (5%):	\$6.95	
		INTEREST A	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.95		
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <u>TERMS</u> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2018-10-09					
				CUSTOMER SIGNATURE	DATE		