

2018-10-11

HST #837181627

DATE 2018-10-11	TECHNICIAN Darren Mann		JOB/ORD 8922	DER#	REFERENCE TEXT Client reference
FIRST NAME jessica		LAST NAME Chow	77		
BILLING ADDRESS COMPANY / BILLING NAME 1005 - 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA	A		1 N V	SERVICE ADDRESS 005 - 1255 SEYMOUR ST IO BUZ /ANCOUVER, V6B0H1 RITISH COLUMBIA, CANADA	
PHONE 604.928.9825	1			MAIL essica_chow1919@hotmail.con	n

## REASON FOR TODAY'S CALL:

Leak in ceiling below kitchen.

## DESCRIPTION OF WORK PERFORMED:

When I arrived onsite there was water in the bottom of the cabinet below the kitchen sink. I tested the sink and found that the water was leaking right through the bottom of the garburator. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator. I then

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$329.00	\$329.00
<i>Q</i>	(1	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$329.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$16.4
			TOTAL:	\$345.45
		We did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALLETOWN PLUMBLING IS NOT RESPONSIBLE FOR BROKEN, SETTLED PLUSTED DETERBORATION, OR LEAD DIDES THE RESPONSIBLE FOR BROKEN,		