



HST #837181627

DATE 2018-10-12	TECHNICIAN Darren Mann		JOB/ORDER # 8919	REFERENCE TEXT Client reference
FIRST NAME Ivan		LAST NAME Simonenko		
BILLING ADDRESS COMPANY / BILLING 2003 - 323 JERVIS ST VANCOUVER, V6C 3F BRITISH COLUMBIA,	- P8		SERVICE ADDRESS 2003 - 323 JERVIS S' VANCOUVER, V6C 3 BRITISH COLUMBIA,	P8
PHONE 604.788.6023			EMAIL ivansimonenko1996@	gmail.com

REASON FOR TODAY'S CALL:

My deck mount bathtub faucet broke. Cold water keeps running even when it turned off (had to shut down cold water). Unfortunately I couldn't find its brand.

DESCRIPTION OF WORK PERFORMED:

The cartridge in the cold handle of the Roman tub filler was broken and would not shut off the flow of water. I replaced the broken cartridge and tested.

TECHNICIAN RECOMMENDATIONS:

*The cause for the cartridge breaking was a thin hard black material that was flowing through the cold supply line in through the cartridge. I flushed out this debris before installing the new cartridge and testing.

QTY.	CODE	DESCRIPTION		PRICE
1		Replace American Standard Amarilis Cartridge		\$159.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		SUBTOTAL:	\$159.00	
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$7.95
		s from your	TOTAL:	\$166.95

Thank You!

invoice and tell us how we did.

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2018-10-12 CUSTOMER SIGNATURE DATE

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,