

(B) @SimplyPlumbing | | YaletownPlumbing



HST #837181627

DATE 2018-10-05	TECHNICIAN Darren Mann		JOB/ORDER # 8870		REFERENCE TEXT Client reference
FIRST NAME Joanna		LAST NAME Marrin			
BILLING ADDRESS COMPANY / BILLING NAME 705 - 1483 HOMER ST VANCOUVER, V6Z 3C7 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  705 - 1483 HOMER ST, BUZZER 1028 THE TENANTS ARE CORRINE AND DOUGLAS TRONSGARD (604-828-61 AND 604-653-6167 RESPECTIVELY) VANCOUVER, V6Z 3C7 BRITISH COLUMBIA, CANADA	
PHONE 1.310.666.3171				EMAIL joannamarrin@yahoo.com	

## REASON FOR TODAY'S CALL:

Replace Roman tub filler in master bathroom.

## DESCRIPTION OF WORK PERFORMED:

I purchased, delivered and installed a new Riobel Roman tub filler. Tested and in good working order.

## TECHNICIAN RECOMMENDATIONS:

Since the drain cleaning service I provided on the last visit the tenants have been able to use the shower and have not experienced any recurrence of the gurgling noise reported previously.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Riobel ED12L	\$470.00	\$470.00
1	12.3	Install Roman Tub Filler	\$300.00	\$300.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$770.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$38.50
		s from your  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$808.50
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

> 2018-10-05 CUSTOMER SIGNATURE DATE