



DATE 2018-10-17	TECHNICIAN Darren Mann	JOB/ORDER # 8927	REFERENCE TEXT Client reference
FIRST NAME natalie		LAST NAME leskinen	
BILLING ADDRESS COMPANY / BILLING NAME 407 - 488 HELMCKEN ST VANCOUVER, V6B6E4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 407 - 488 HELMCKEN ST, BUZZER #047 VANCOUVER, V6B6E4 BRITISH COLUMBIA, CANADA	
PHONE 604-506-3480		EMAIL natalieleskinen@hotmail.com	

REASON FOR TODAY'S CALL:
Toilet not secure to the floor.

DESCRIPTION OF WORK PERFORMED:
When I lifted the toilet I found the floor flange to be broken on either side where the bolts attach. I cleaned the area under the toilet, installed a repair floor flange, then reinstalled the toilet using a MaxWax wax ring and braided supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Wax Seal - Standard	\$189.00	\$189.00
1		Toilet Floor Flange Repair	\$59.00	\$59.00
			SUBTOTAL:	\$248.00
			GST (5%):	\$12.40
			TOTAL:	\$260.40

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-10-17

CUSTOMER SIGNATURE

DATE