

(SimplyPlumbing f YaletownPlumbing

## HST #837181627

DATE 2018-10-19	TECHNICIAN Darren Mann		JOB/ORDER # 8944		REFERENCE TEXT 18-1423	
FIRST NAME Advent		LAST NAME Admin	7			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 320 - 1330 BURRARD ST, BUZ#320 JEFFREY BUNN: 604.360.7929 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478			EMAIL andrea@adventvancouver.com			

REASON FOR TODAY'S CALL: Shower bar detaching from wall.

## DESCRIPTION OF WORK PERFORMED:

One of the screws securing the shower bar rusted out. I removed this screw, installed a new one and siliconed around the connection to the tile.

<b>QTY</b> .	CODE		DESCRIPTION				PRICE
1		Discount Labour				\$99.00	\$99.00
Guve us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$99.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUT		GST (5%):	\$4.95	
		INTERECT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95		
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETILED, RUSTED, DETERIORATION, OR LEAD PIPES, FLYTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2018-10-19					
				CUSTOMER SIGNATURE	DATE		