



DATE 2018-11-23	TECHNICIAN Darren Mann	JOB/ORDER # 9012	REFERENCE TEXT Client reference
FIRST NAME Barbara		LAST NAME Freedman	
BILLING ADDRESS COMPANY / BILLING NAME 801 - 431 PACIFIC ST VANCOUVER, V6Z2P6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 801 - 431 PACIFIC ST VANCOUVER, V6Z2P6 BRITISH COLUMBIA, CANADA	
PHONE 604.685.3737		EMAIL bfree@shaw.ca	

REASON FOR TODAY'S CALL:
Toilet leaking to floor below.

DESCRIPTION OF WORK PERFORMED:
I lifted the toilet and found the wax seal to be compromised, allowing water to seep out between the bowl and the floor during a flush. I re-set the toilet with a new MaxWax wax ring and braided supply line. During testing I found the toilet fillvalve to be spraying out of the top. I replaced this fillvalve and tested again.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Wax Seal - Standard	\$189.00	\$189.00
1	9520164	PRO45B ANTI-SYPH FILL VLV UQ	\$35.00	\$35.00
SUBTOTAL:			\$224.00	\$224.00
GST (5%):			\$11.20	\$11.20
TOTAL:			\$235.20	\$235.20

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2018-11-23 _____
 CUSTOMER SIGNATURE DATE