

HST #837181627

DATE 2018-11-26	TECHNICIAN Darren Mann		JOB/ORDER # 9017		FERENCE TEXT 1610	
FIRST NAME Advent		LAST NAME Admin				
BILLING ADDRESS ADVENT REAL ESTATE SERV #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		HANNAH: 6 MATT: 604.: VANCOUVE	NICOLA ST, BUZ1079 04.349.6832 349.0989			
PHONE 604.736.6478			EMAIL andrea@ad	ventvancouver.com		

REASON FOR TODAY'S CALL:

Leak under kitchen sink.

DESCRIPTION OF WORK PERFORMED:

I found the leak to be coming from a small tear in the 1/4? filtered water supply. The tear was right at the connection to the filter housing. I cut the tear out, installed a new brass insert and reattached. Tested and no other leaks detected.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	// .	Discount Labour		\$99.00	\$99.00
Gwe us Feedback Please visit our feedback page at:		'aa 10 - ala	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$99.00
				GST (5%):	\$4.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$103.95		
	tell us how		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		
			CUSTOMER SIGNATURE DATE		