

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2018-12-03	TECHNICIAN Darren Mann		JOB/ORDER # 9019		REFERENCE TEXT Client reference
FIRST NAME Carolyn		LAST NAME Levy	2		
BILLING ADDRESS COMPANY / BILLING NAME 3258 WEST 8TH AVE VANCOUVER, V6K2C5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 3258 WEST 8TH AVE VANCOUVER, V6K2C5 BRITISH COLUMBIA, CANADA	
PHONE 604.739.3317 (home)				EMAIL carolynl@telus.net	

REASON FOR TODAY'S CALL:

We need a cartridge replacement on a single pullout faucet (Grohe). Replacement cartridge is on hand. We're having trouble removing parts on faucet. We also need to replace a cartridge on a leaking shower. We have the cartridge but need the plumber to do the actual replacement.

DESCRIPTION OF WORK PERFORMED:

-I replaced the Thermostatic cartridge in the master ensuite shower and tested. -I replaced the cartridge within the kitchen faucet and tested.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1	1	Install Thermostation	c Cartridge			\$159.00	\$159.00
0		and a du	WARRANTY:	Y: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$159.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		GST (5%):	\$7.95	
		INTEREST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$166.95	
	tell us how v		MATERIALS L SETTLED, RU RESULTING F	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS N ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIF CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOU . & O. E. CUSTOMER SIGNATURE	IOT RESPONSIBLE FOR BROKEN, I OUTS AND ANY OTHER DAMAGES PING.		
				CUSTOMER SIGNATURE			