





HST #837181627

DATE 2018-12-11	TECHNICIAN Darren Mann		JOB/ORDER # 9036	REFERENCE TEXT Client reference	
FIRST NAME Jayne		LAST NAME Griffiths			
BILLING ADDRESS COMPANY / BILLING NAME 108 - 655 WEST 13TH AVE VANCOUVER, V5Z 1N8 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 108 - 655 WEST 13TH AVE, BUZZER 128 VANCOUVER, V5Z 1N8 BRITISH COLUMBIA, CANADA		
PHONE 778.318.8733			EMAIL Jgriffiths1483@gmail	EMAIL Jgriffiths1483@gmail.com	

REASON FOR TODAY'S CALL:

Bath making a gurgling sound when toilet is flushed and also sink in bathroom is draining really slowly.

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from the tub and lavatory sink drains. *The tub drain felt like there may be a hard object of some sort stuck inside the P-trap but I was able to push past it.

QTY.	CODE	DESCRIPTION			PRICE
1		Clean drain using Pow	verSpin / Lavatory	\$139.00	\$139.00
invoice and tell us how we did.		and and wa	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.95
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT VALETOWN PLUMRING IS NOT RESPONSIBLE FOR BROKEN		

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2018-12-11

CUSTOMER SIGNATURE

DATE