

(B) @SimplyPlumbing | | YaletownPlumbing

HST #837181627

DATE 2018-12-12	TECHNICIAN Darren Mann		JOB/O 9042	RDER #	REFERENCE TEXT 18-1722
FIRST NAME Advent		LAST NAME Admin	7		
BILLING ADDRESS ADVENT REAL ESTATE SERV #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA	19	4	SERVICE ADDRESS 902 - 1055 HOMER ST ALANNA: 604.417.0702 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Garburator not working.

DESCRIPTION OF WORK PERFORMED:

The garburator grinding chamber was rusted to the point that bits of metal were breaking off. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2H	oply & Install 1/2HP Waste King 1001 Garburator		
Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. INTEREST AT THE LEGAL RATE IS MADE THAT SERVICES LISTED AB MATERIALS LISTED HEREON ARE SETTLED, RUSTED, DETERIORATI RESULTING FROM CLEANING OR		and a oly	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY	GST (5%):	\$13.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. NTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HER	TOTAL:	\$292.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROK SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAM RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. (ERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK	EN,	

CUSTOMER SIGNATURE

DATE