



DATE 2018-12-20	TECHNICIAN Darren Mann	JOB/ORDER # 9058	REFERENCE TEXT 18-1756
FIRST NAME Advent		LAST NAME Admin	
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 703 - 518 MOBERLY RD, BUZ1098 KELLISA: 1.306.514.1175 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478		EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:
Tub fills when lavatory sink used.

DESCRIPTION OF WORK PERFORMED:
-I ran the PowerSpin drain snake through the lavatory sink drain and cleared the blockage that was affecting the tub and lavatory drains. Tested by filling the sink and draining multiple times, as well as filling the tub 8? and draining. -The lavatory faucet aerator was spraying out of the side, I installed a new aerator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Discount Labour	\$99.00	\$99.00
1		Lavatory Aerator	\$10.00	\$10.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45

_____ 2018-12-20
 CUSTOMER SIGNATURE DATE