

(SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2019-01-03	TECHNICIAN Darren Mann		JOB/ORDER # 9075		REFERENCE TEXT Client reference
FIRST NAME Rosemary		LAST NAME Shih	7		
BILLING ADDRESS COMPANY / BILLING NAME 5962 CHANCELLOR BLVD VANCOUVER, V6T 0A1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 5962 CHANCELLOR BLVD VANCOUVER, V6T 0A1 BRITISH COLUMBIA, CANADA	
PHONE 604.813.3331				EMAIL Rosemaryshih@yahoo.ca	

REASON FOR TODAY'S CALL: Garburator leaking through bottom.

## DESCRIPTION OF WORK PERFORMED:

I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator			\$329.00
Guve us Geedback   Please visit our feedback page at:   www.yaletownplumbing.com/feedback   [1]   Fill in the required details from your   invoice and tell us how we did.   Thank You!		and a du	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$329.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$16.45
		.com/feedback [1]	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$345.45
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		