

HST #837181627

UNIT PRICE

PRICE

DATE 2019-01-03			JOB/ORDER # 9083		REFERENCE TEXT 19-0013
FIRST NAME Advent		LAST NAME Admin	7		
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		<u> </u>	4	SERVICE ADDRESS 2103 - 989 BEATTY ST KEYS AVAILABLE AT OFFICE. VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Guest bathroom toilet stopper is not flushing.

DESCRIPTION OF WORK PERFORMED:

CODE

QTY.

The flapper was warping and the fillvalve was making a loud noise when the tank was filling. I replaced the fillvalve, flapper, and supply line. Tested and in good working order.

DESCRIPTION

1		Discount Labour	\$99.00	\$99.00
1	2121352	B1-16DL 3/8X20 SPEEDI+ WC CONN	\$11.00	\$11.00
1	9520164	PRO45B ANTI-SYPH FILL VLV UQ	\$35.00	\$35.00
1		Kohler Blue Flapper W Float	\$15.00	\$15.00
<i>Q</i>	o (I	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$160.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS. 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$8.00
			TOTAL:	\$168.00

<u> Thank You!</u>

invoice and tell us how we did.

RESOLUTION OF THE VIEW OF THE VIEW OF THE PROPERTY OF THE PROP
RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,
MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND
INTEREST AT THE LEGAL RATE IS CHARGED ON FAST DUE ACCOUNTS. ACKNOWLEDGEWENT IS HEREBT

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CUSTOMER SIGNATURE