



DATE 2019-01-03	TECHNICIAN Darren Mann	JOB/ORDER # 9077	REFERENCE TEXT Client reference
FIRST NAME Victoria		LAST NAME Bryan	
BILLING ADDRESS COMPANY / BILLING NAME 404 - 1180 HOMER ST. VANCOUVER, V6B2X6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 404 - 1180 HOMER ST., BUZZER 248 VANCOUVER, V6B2X6 BRITISH COLUMBIA, CANADA	
PHONE 604.762.5499		EMAIL vbryan@me.com	

REASON FOR TODAY'S CALL:

Hi--We've got a slow leak from one of the water valves under the left side sink in our master bath (this is the same sink that you recently had to fix due to it being plugged).

DESCRIPTION OF WORK PERFORMED:

The hot shut off valve under the left lavatory sink in the master bathroom was leaking from the stem and nut. I repaired this valve by replacing the washer, stem, packing, packing nut, and handle.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

V. Bryan

2019-01-03

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95