



DATE 2019-01-04	TECHNICIAN Darren Mann	JOB/ORDER # 9081	REFERENCE TEXT Client reference
FIRST NAME Cecilia	LAST NAME Achiam		
BILLING ADDRESS COMPANY / BILLING NAME 1915 WEST 13TH AVE VANCOUVER, V6J 2H5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 202 - 1720 BARCLAY ST, BUZ#202 ERIN(TENANT): 778.885.5193 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.233.7909	EMAIL cachiam@richmond.ca		

REASON FOR TODAY'S CALL:
Kitchen sink basket strainer broken.

DESCRIPTION OF WORK PERFORMED:
When I removed the broken basket strainer assembly I found that parts of the drainage were corroding as well. I replaced the basket strainer and repiped the ABS drainage. Tested by filling and draining the sink multiple times.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Kitchen Sink Basket Strainer Assembly & Re-Pipe ABS Drainage	\$179.00	\$179.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$179.00
GST (5%):	\$8.95
TOTAL:	\$187.95

_____ 2019-01-04

 CUSTOMER SIGNATURE DATE