



DATE 2018-12-13	TECHNICIAN Darren Mann	JOB/ORDER # 9044	REFERENCE TEXT Client reference
FIRST NAME Frederick		LAST NAME Fajardo	
BILLING ADDRESS COMPANY / BILLING NAME 401 - 1236 BIDWELL ST VANCOUVER, V6G 2K9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 401 - 1236 BIDWELL ST, BUZZER 401 VANCOUVER, V6G 2K9 BRITISH COLUMBIA, CANADA	
PHONE 604-644-0904		EMAIL Frederickfajardo@gmail.com	

REASON FOR TODAY'S CALL:
 -Garburator jammed. -Upstairs shower won't fully shut off.

DESCRIPTION OF WORK PERFORMED:
 DEC13: -I removed glass from the garburator grinding chamber and tested by filling and draining the sink while running the garburator. -I took pictures of the shower valve and will contact Riobel and inquire about replacement parts. JAN7: I installed the new Riobel Thermostatic cartridge and securing nut. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
1		Replace Thermostatic Cartridge - Riobel	\$159.00	\$159.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

Frederick Fajardo

 CUSTOMER SIGNATURE

2018-12-13

DATE

SUBTOTAL:	\$268.00
GST (5%):	\$13.40
TOTAL:	\$281.40