

(B) @SimplyPlumbing | | YaletownPlumbing

HST #837181627

DATE 2019-01-11	TECHNICIAN Darren Mann		JOB/ORDER # 9114	REFERENCE TEXT 19-0063	
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 905 - 1255 SEYMOUR ST, BUZ#750* DARAH: 778.834.0013 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478		EMAIL andrea@adventvance	EMAIL andrea@adventvancouver.com		

REASON FOR TODAY'S CALL:

Bathtub drain stopper: Plug is not tight and no longer holder water

DESCRIPTION OF WORK PERFORMED:

The tub drain stopper was broken. Also there was a notice sent out to owners of the Elan a couple years ago suggesting the replacement of their tub drains as a number of the original drains were causing leakage issues. I replaced the tub drain trim with a new lift and turn style drain assembly and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tub Drain Trim - Standard		\$159.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$159.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$7.95
			TOTAL:	\$166.95
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED BLISTED DETERIORATION OF LEAD PURES. CLEAN OUTS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE

DATE