



DATE 2019-01-17	TECHNICIAN Darren Mann	JOB/ORDER # 9123	REFERENCE TEXT Client reference
FIRST NAME David		LAST NAME Yang	
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 705 - 193 AQUARIUS MEWS KEYS AVAILABLE AT OFFICE. VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.988.8470		EMAIL PMVan1@rentitfurnished.com	

REASON FOR TODAY'S CALL:
Toilet tank not filling after flush.

DESCRIPTION OF WORK PERFORMED:
The fillvalve was not properly filling the tank after a flush and the flapper was starting to warp. I replaced the fillvalve, flapper, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet FillValve, Flapper, Supply - Standard	\$169.00	\$169.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45

_____ 2019-01-17

 CUSTOMER SIGNATURE DATE