

(B) @SimplyPlumbing | | YaletownPlumbing

HST #837181627

DATE 2019-01-18	TECHNICIAN Darren Mann		JOB/ORDER # 9126	REFERENCE TEXT 19-0102
FIRST NAME Advent		LAST NAME Admin		·
BILLING ADDRESS ADVENT REAL ESTA #204 - 1168 HAMILTO VANCOUVER, V6B2S BRITISH COLUMBIA,	ON ST S2		SERVICE ADDRESS  1101 - 1211 MELVIL MIN: 1.403.926.8102 VANCOUVER, BRITISH COLUMBIA	LE ST
PHONE 604.736.6478			EMAIL andrea@adventvand	couver.com

## REASON FOR TODAY'S CALL:

Garburator cracked, Leaking. \*Drain is also clogged.

## DESCRIPTION OF WORK PERFORMED:

The kitchen sink drain was blocked. I used a PowerSpin drain snake to clear the blockage. I replaced the cracked garburator with a new Waste King 1001 and tested by filling and draining both sides of the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator		\$279.00
<i>Q.</i>		eedback Warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00
	t our feedbac	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$13.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank Youl			TOTAL:	\$292.95
		WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED PLISTED DETERIORATION OR LEAD PIPES FIXTURES CLEAN OUTS AND ANY OTHER DAMAGES.	;	

CUSTOMER SIGNATURE

DATE