



DATE 2019-01-25	TECHNICIAN Darren Mann	JOB/ORDER # 9143	REFERENCE TEXT 19-0150
FIRST NAME Advent		LAST NAME Admin	
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1001 - 1001 RICHARDS ST SAHIL: 604.785.9885 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478		EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:
Lavatory drain stopper stuck in closed position.

DESCRIPTION OF WORK PERFORMED:
The drain is a push style drain. The handyman who visited the unit the day before was unaware of this. He removed the drain assembly from the sink and was trying to push the drain stopper out from the bottom. I cleaned off the drain assembly and reinstalled. Tested by filling and draining the sink multiple times.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Discount Labour	\$99.00	\$99.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95

_____ 2019-01-25

 CUSTOMER SIGNATURE DATE