

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

DATE 2019-01-29	TECHNICIAN Darren Mann		JOB/ORDER # 9147	REFERENCE TEXT Client reference
FIRST NAME Jason		LAST NAME King		
BILLING ADDRESS COMPANY / BILLING NAME 1907 - 193 AQUARIUS MEWS VANCOUVER, V6Z 2Z2 BRITISH COLUMBIA, CANADA			SERVICE ADDRES 1907 - 193 AQUAR VANCOUVER, V6Z BRITISH COLUMB	IUS MEWS, BUZZER 1117 Z 2Z2
PHONE 604.783.8741			EMAIL g8nigazi@hotmail.c	com

REASON FOR TODAY'S CALL:

I've looked closely at the supply line and I'm pretty sure the water is slowly coming out of the nut that's connecting the supply line to the shut off valve. It's where I know the toilet paper gets wet after I dry off the line. But also, the entire steel supply line is rusted and dirty and not sure why that is, but I'm sure you will know more

DESCRIPTION OF WORK PERFORMED:

The toilet supply line was leaking, the fillvalve was taking a long time to fill the tank after each flush, and the flapper was warping. I replaced the fillvalve, flapper, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Replace Toilet FillValve, Flapper, Supply - Standard	\$169.00	\$169.00
0		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Thank Your		k page at: LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.45
			TOTAL:	\$177.45
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREI	N,	

CUSTOMER SIGNATUR

2019-01-29

CHARGES. E. & O. E.