

2019-02-01

DATE

HST #837181627

DATE 2019-02-01	TECHNICIAN Darren Mann		JOB/ORDER # 9139	REFERENCE TEXT Client reference	
FIRST NAME Carolyn		LAST NAME Levy			
BILLING ADDRESS COMPANY / BILLING 3258 WEST 8TH AVE VANCOUVER, V6K2C BRITISH COLUMBIA,	C5	79	SERVICE ADDRESS 3258 WEST 8TH AVE VANCOUVER, V6K20 BRITISH COLUMBIA,	: C5	
PHONE 604.739.3317 (home)			EMAIL carolynl@telus.net		

REASON FOR TODAY'S CALL:

Replace thermostatic cartridge housing.

DESCRIPTION OF WORK PERFORMED:

The screws that were broken off in the valve cover were completely seized in place and could not be removed. I installed the new SP HG (88723000) cartridge and

QTY.	CODE		DESCRIPTION		
1	/	Labour		\$109.00	\$109.0
Gure	us F	eedback	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.0
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.4
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.4
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE