

HST #837181627

DATE 2019-02-15	TECHNICIAN Darren Mann		JOB/ORDER # 9183	REFERENCE TEXT Client reference
FIRST NAME Ben		LAST NAME Hulse		
BILLING ADDRESS COMPANY / BILLING NAME 1705 - 688 ABBOTT ST VANCOUVER, V6B0B9 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1705 - 688 ABBOTT ST, BUZZER 330 VANCOUVER, V6B0B9 BRITISH COLUMBIA, CANADA	
PHONE 778.834.5565			EMAIL ben@benhulse.com	

REASON FOR TODAY'S CALL:

Hi Darren, I?ve got a toilet that is acting up over here. Water level drops in take slowly and refills every 3 minutes or so. I tried replacing the flapper today but no clear improvement.

DESCRIPTION OF WORK PERFORMED:

The fillvalve overflow hose wasn?t cut during installation. The full length of the hose was pushed down the flushvalve overflow tube and was causing a siphone that slowly sucked water out of the tank.

QTY.	CODE	DESCRIPTION			PRICE
1		Discount Labour		\$99.00	\$99.00
Q	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		SUBTOTAL:	\$99.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$4.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95
		,	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK		

CUSTOMER SIGNATURE

DATE