

HST #837181627

DATE 2019-02-26	TECHNICIAN Darren Mann		JOB/O 9187	RDER #	REFERENCE TEXT Client reference
FIRST NAME Alice		LAST NAME Jia			
BILLING ADDRESS COMPANY / BILLING NAME 975 BEATTY ST VANCOUVER, V6Z3C5 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 975 BEATTY ST VANCOUVER, V6Z3C5 BRITISH COLUMBIA, CANADA	
PHONE 778.986.7634				EMAIL weiting27@icloud.com	

REASON FOR TODAY'S CALL: Bathroom tub is draining slow.

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from the drain and tested by filling the tub 8? and draining.

i doca tile i	oworopin drai	in shake to clear hall h	Tom the drain	rand tested by mining the tub or and draming.		
QTY.	CODE		UNIT PRICE	PRICE		
1		Clean drain using PowerSpin / Tub/Shower				\$139.00
Gwe us Feedback Please visit our feedback page at:			WARRANTY:	ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		\$139.00
				LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		INTEREST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$145.95	
		MADE THAT S MATERIALS L SETTLED, RU RESULTING F	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, JISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			

CUSTOMER SIGNATURE

2019-02-26

DATE