

HST #837181627

DATE 2019-03-06	TECHNICIAN Darren Mann		JOB/ORDER # 9214		REFERENCE TEXT Client reference
FIRST NAME Ross		LAST NAME Lawrie			
BILLING ADDRESS COMPANY / BILLING NAME 2305 - 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS  2305 - 1255 SEYMOUR ST, BUVANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA	
PHONE 604.720.9795				EMAIL rlawrie@me.com	

REASON FOR TODAY'S CALL:

Garburator cracked.

## **DESCRIPTION OF WORK PERFORMED:**

I installed the new garburator, repiped a portion of the ABS drainage, and used a Waste King drain 90 kit to accommodate the distance between the garburator drain outlet and the ABS slipjoint adaptor. Tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2HP Badg	\$329.00	\$329.00	
1	1/2	ABS Fittings & Waste King G	Carburator 90	\$25.00	\$25.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your		warranty	: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$354.00
				GST (5%):	\$17.70
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$371.70

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES, E. & O. E.

2019-03-06

CUSTOMER SIGNATURE

DATE