

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

DATE 2019-03-22	TECHNICIAN Darren Mann		JOB/ORDER # 9266		REFERENCE TEXT Client reference
FIRST NAME Kelly		LAST NAME Shin	7		
BILLING ADDRESS COMPANY / BILLING NAME 1705 - 1438 RICHARDS ST VANCOUVER, V6Z 3B8 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 1705 - 1438 RICHARDS ST, BU VANCOUVER, V6Z 3B8 BRITISH COLUMBIA, CANADA	
PHONE 604.763.2402				EMAIL kel_shin@hotmail.com	

REASON FOR TODAY'S CALL:

We want to change our shower handle. Unfortunately, the screw that connected the shower handle to the valve (?) was rusted and broke off. We tried to remove the broken screw by drilling into it and using a screw extractor but was unsuccessful. We hope you can help us connect the new shower handle by whatever method necessary. (Removing the broken screw, replacing the valve, or whatever.) Please let us know what options we have? Attached photos of shower and newly purchased handle.

DESCRIPTION OF WORK PERFORMED:

I replaced the mixing & pressure balance cartridges and reinstalled the original handle. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	// .	Replace Mixing & Pressure Balance Cartridge - HC180	\$229.00	\$229.00
Rung	(1	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$229.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$11.45
			TOTAL:	\$240.45
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN		

2019-03-22