

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2019-03-25	TECHNICIAN Darren Mann		JOB/O 9270	RDER #	REFERENCE TEXT Client reference	
FIRST NAME Maryann		LAST NAME Treffers	7			
BILLING ADDRESS COMPANY / BILLING NAME 2502 - 1033 MARINASIDE CRES VANCOUVER, V6Z 3A3 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2502 - 1033 MARINASIDE CRES, BUZZER 1667 VANCOUVER, V6Z 3A3 BRITISH COLUMBIA, CANADA		
PHONE 604.928.0981				EMAIL maryanntreffers@gmail.com		

REASON FOR TODAY'S CALL: Clogged toilet.

DESCRIPTION OF WORK PERFORMED:

I used the 6? toilet auger to clear the toilet blockage.

TECHNICIAN RECOMMENDATIONS:

The toilet is cracked, loose on the floor, and has issues within the tank. I?ve suggested replacing the toilet asap. The following measurements will be required when shopping for a new toilet: Elongated, 13? rough in, 31.5? from floor to bottom of countertop, 30.5? from floor to wood support under countertop.

QTY .	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	11	Clear toilet blockag	\$139.00	\$139.00	
Runs of Goodle al			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
		.com/feedback [1]	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALEATOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		