

HST #837181627

DATE 2019-03-27	TECHNICIAN Darren Mann		JOB/ORDER # 9279	REFERENCE TEXT 19-0470	
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			804 - 63 WEST 2 BARBARA: 604. VANCOUVER,	SERVICE ADDRESS  804 - 63 WEST 2ND AVE, BUZ#3072 BARBARA: 604.828.6960 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478			EMAIL andrea@adventy	vancouver.com	

REASON FOR TODAY'S CALL: Handheld shower holder leaking.

DESCRIPTION OF WORK PERFORMED:

I replaced the broken shower head holder and tested.

QTY.	CODE	DESCRIPTION			PRICE
1	//	Discount Labour		\$99.00	\$99.00
1	1/2	Luxart Handheld Shower	Holder	\$30.00	\$30.00
		warra	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$6.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$135.45
		INTER	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$ CHARGES. E. & O. E.

2019-03-27