



HST #837181627

DATE 2019-04-04	TECHNICIAN Darren Mann		JOB/ORDER # 9292		REFERENCE TEXT Client reference
FIRST NAME Colin		LAST NAME Doig			
BILLING ADDRESS RE/MAX CREST REALTY WESTSIDE 1428 WEST 7TH AVE VANCOUVER, V6H1C1 BRITISH COLUMBIA, CANADA		4	SERVICE ADDRESS 3304 - 1189 MELVILLE ST, BUZ#200 ARDALAN: 604.771.6699 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.417.9003				EMAIL colin@colindoig.com	

REASON FOR TODAY'S CALL:

Toilet tank not filling correctly.

DESCRIPTION OF WORK PERFORMED:

The toilet shut off valve was starting to fail, the fillvalve was not fully shutting the water off when the tank was full, and the flapper was starting to warp. I first repaired the wc shut off valve by replacing the washer, stem, packing, packing nut, and handle. I then installed a new fillvalve, flapper, and braided supply line. Tested and in good working order.

QTY.	CODE		UNIT PRICE	PRICE	
1	1.	Replace Toilet FillValve, Flapper, Supply - Standard			\$169.00
1		Repair 1/2" x 3/8" Angle or Stra	\$25.00	\$25.00	
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$194.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.70
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$203.70

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2019-04-04 CUSTOMER SIGNATURE DATE