

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2019-04-09	TECHNICIAN Darren Mann		JOB/O 9305	RDER#	REFERENCE TEXT Client reference	
FIRST NAME Charmaine		LAST NAME Spencer	97			
BILLING ADDRESS COMPANY / BILLING NAME 408 - 1003 BURNABY ST VANCOUVER, V6E4R7 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 408 - 1003 BURNABY ST, BUVANCOUVER, V6E4R7 BRITISH COLUMBIA, CANAD		
PHONE 778.558.0715				EMAIL cspencer@shaw.ca		

REASON FOR TODAY'S CALL: Jammed garburator.

DESCRIPTION OF WORK PERFORMED:

-I removed what appeared to be an old rusty nail from the garburator grinding chamber and tested. -The hot water pressure in the kitchen faucet is very low. I believe the hot shut off valve is breaking down internally and will require repair. Unfortunately the main water shut off valves were not accessible on this visit

QTY.	CODE		UNIT PRICE	PRICE	
1		Discount Labour		\$99.00	\$99.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$99.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.9
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95
		we did.	EREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY DE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND TERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, TLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES SULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.		

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

Thank You!

hamain Spencer

2019-04-09

CUSTOMER SIGNATURE

DATE