



DATE 2019-04-24	TECHNICIAN Darren Mann	JOB/ORDER # 9330	REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal	
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1002 - 1228 WEST HASTINGS ST, BUZ#133 GABRIELE: 604.779.7552 GBRENCHER@GMAIL.COM VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.0141		EMAIL PMVan2@rentitfurnished.com	

REASON FOR TODAY'S CALL:
 Tub and lavatory sinks not draining well. *grab keys from office

DESCRIPTION OF WORK PERFORMED:
 -The toilet fillvalve in the guest bathroom was spraying out of the top. I replaced this fillvalve, installed a new braided supply line, and tested. -I removed hair from the top of the lavatory and tub drains in the master bathroom and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace toilet FillValve - standard	\$159.00	\$159.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$159.00
GST (5%):	\$7.95
TOTAL:	\$166.95

_____ 2019-04-24
 CUSTOMER SIGNATURE DATE