

(SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2019-05-03	TECHNICIAN Darren Mann		JOB/O 9370	RDER #	REFERENCE TEXT Client reference
FIRST NAME Adam		LAST NAME Khalfalla (Ikari)	7		
BILLING ADDRESS COMPANY / BILLING NAME 2205 - 1288 WEST GEORGIA S VANCOUVER , V6E 4R8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 804 - 1200 WEST GEORGIA ST DESA: 604.834.0222 VANCOUVER , V6E 4R2 BRITISH COLUMBIA, CANADA	
PHONE 604.715.5559				EMAIL k.adam@mail.com	

REASON FOR TODAY'S CALL: Replace shower valve trim.

DESCRIPTION OF WORK PERFORMED:

I installed the new Grohe shower valve trim and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$139.00	\$139.00
1	6	Grohe Bauloop Trim	\$139.00	\$139.00
1		Grohe Valve Cover	\$110.00	\$110.00
			SUBTOTAL	¢299.00

Gwe us Feedback	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$388.00
Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$19.40
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$407.40
invoice and tell us how we did. <u>Thank You!</u>	MADE THAT S MATERIALS L SETTLED, RU RESULTING F	THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES ROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK & O. E.		

CUSTOMER SIGNATURE

2019-05-03

DATE