

Phone: 604.727.4484 yaletownplumbing.com

(a) @SimplyPlumbing **F** YaletownPlumbing

HST #837181627

10741

DATE 2019-06-04	TECHNICIAN Darren Mann		JOB/OI 9451	RDER #	REFERENCE TEXT	
FIRST NAME Dawn		LAST NAME Mackenzie	7			
BILLING ADDRESS			1.	SERVICE ADDRESS		
306 - 928 BEATTY ST VANCOUVER, V6Z3G6 BRITISH COLUMBIA, CANADA			9	306 - 928 BEATTY ST ,BUZ#1012 VANCOUVER, V6Z3G6 BRITISH COLUMBIA, CANADA		
PHONE 778.552.6517				EMAIL dawnmarie_mackenzie@yahoo.	ca	

REASON FOR TODAY'S CALL:

The toilet is not filing properly and when it flushes it fills all the way to the top and then flushes again all by itself. Worried it is going to overflow

DESCRIPTION OF WORK PERFORMED:

The fillvalve wasn?t fully shutting off on some flushes and the flapper was warping. I replaced the fillvalve, flapper, and supply line. Tested and in good working order.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet FillVa	lve, Flapper, Supply - Standard	\$169.00	\$169.00
0	a	and had	IARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Guve us Jeedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$177.45
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <u>TERMS</u> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		
			2019-06-04		
			CUSTOMER SIGNATURE DATE		