

(B) @SimplyPlumbing | YaletownPlumbing

2019-06-04

DATE

HST #837181627

DATE 2019-06-04	TECHNICIAN Darren Mann		JOB/ORDER # 9452	REFERENCE TEXT	
FIRST NAME Lynn		LAST NAME Purdy			
BILLING ADDRESS 2804 WHISKEY POINT ROAD MILLA BAY, V0R2P2 BRITISH COLUMBIA, CANADA			#2202 - 1005 BEACH AVE BUZ#1196 UTE H: 604.336.2444 C: 778.996.5103 MILLA BAY, BRITISH COLUMBIA, CANADA		
PHONE 1.250.743.7176			EMAIL Idpurdey@gmail.com		

REASON FOR TODAY'S CALL:

The toilet in the hallway is running, also the tank doesn't seem to fill properly.

DESCRIPTION OF WORK PERFORMED:

The fillvalve was not fully shutting off when the tank was full and the flushvalve gasket was starting to warp. I replaced the fillvalve, flushvalve gasket, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION			PRICE
1	1/2	Replace Toilet FillValve, Flapper, Supply - Standard		\$169.00	\$169.00
<i>Q</i>		and and	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO				GST (5%):	\$8.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$177.45
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE