

(SimplyPlumbing f YaletownPlumbing

## HST #837181627

DATE 2019-06-18	TECHNICIAN Darren Mann		JOB/ORDER # 9476		REFERENCE TEXT Client reference	
FIRST NAME lain		LAST NAME Barr	7			
BILLING ADDRESS COMPANY / BILLING NAME 413 - 2851 HEATHER ST VANCOUVER, V5Z0A2 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 413 - 2851 HEATHER ST, BUZ0433 VANCOUVER, V5Z0A2 BRITISH COLUMBIA, CANADA		
PHONE 604.876.7577				EMAIL ibarr@telus.net		

REASON FOR TODAY'S CALL:

The drain under the kitchen sink is leaking.

## DESCRIPTION OF WORK PERFORMED:

There was a hairline crack in the ABS p-trap fitting under the kitchen sink. I replaced this fitting and tested by filling and draining the sink multiple times. No other leaks were detected.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Replace 1.5? ABS	Ptrap			\$129.00	\$129.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	SUBTOTAL:	\$129.00		
					GST (5%):	\$6.45	
				TOTAL:	\$135.45		
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.					
				CUSTOMER SIGNATURE	DATE		