

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2019-07-03	TECHNICIAN Darren Mann		JOB/ORDER # 9502		REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal	7		
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 302 - 1388 NELSON ST, BUZ24 RODRIGO: 778.751.1365 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.0141				EMAIL PMVan2@rentitfurnished.com	

REASON FOR TODAY'S CALL:

Master bathroom tub and sink draining slowly.

DESCRIPTION OF WORK PERFORMED:

I removed hair from the top of the lavatory and tub drains in the master bathroom.

TECHNICIAN RECOMMENDATIONS:

I showed the tenants how to remove the drain stoppers so they can remove hair themselves in the future.

QTY.	CODE	DESCRIPTION				PRICE
1	11	Discount Labour			\$99.00	\$99.00
Gwe us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$99.00	
				GST (5%):	\$4.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95	
		MATERIALS SETTLED, RU RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK : & O. E. 2019-07-03			
				CUSTOMER SIGNATURE DATE		