



10783

HST #837181627

DATE 2019-07-05	TECHNICIAN Darren Mann	JOB/ORDER # 9488	REFERENCE TEXT Client reference
FIRST NAME Stephen		LAST NAME Heeney	
BILLING ADDRESS COMPANY / BILLING NAME #2903 - 1500 HORNBY ST VANCOUVER, V6Z 2R1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2903 - 1500 HORNBY ST, BUZZER 3130 VANCOUVER, V6Z 2R1 BRITISH COLUMBIA, CANADA	
PHONE 604.681.5344		EMAIL sheeney@novuscom.net	

REASON FOR TODAY'S CALL:  
Guest bathroom toilet running.

DESCRIPTION OF WORK PERFORMED:  
The guest bathroom toilet fillvalve was not fully shutting off on some flushes, causing the toilet to run. I replaced the FillValve and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace toilet FillValve - standard	\$159.00	\$159.00
SUBTOTAL:				\$159.00
GST (5%):				\$7.95
TOTAL:				\$166.95

**Give us Feedback**

Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.

**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

\_\_\_\_\_ 2019-07-05  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE DATE