

HST #837181627

DATE 2019-07-17	TECHNICIAN Darren Mann		JOB/ORDER # 9519	REFERENCE TEXT Client reference	
FIRST NAME Karim		LAST NAME Allibhai			
BILLING ADDRESS COMPANY / BILLING NAME 4238 CARLETON AVE BURNABY, V5G3B6 BRITISH COLUMBIA, CANADA		302 - 1009 HARW MARIONNA: 1.77 MARIONA.RUBIO BURNABY,	SERVICE ADDRESS  302 - 1009 HARWOOD ST, BUZ#0302 MARIONNA: 1.778.323.0250 MARIONA.RUBIO@GMAIL.COM BURNABY, BRITISH COLUMBIA, CANADA		
PHONE 604.961.2228			EMAIL karim.allibhai@gn	nail.com	

## REASON FOR TODAY'S CALL:

Shower valve handle loose, falls off. Issues with pressure in same shower.

## DESCRIPTION OF WORK PERFORMED:

I was able to reattach the loose handle and replaced the shower head with new.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Labour		\$109.00	\$109.00
1	11	Delta Shower Head		\$20.00	\$20.00
<i>Q</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$129.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$6.45
		s from your			\$135.45

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. AC MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AN MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN O RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPIN TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR,	ND THAT CHARGES AND RESPONSIBLE FOR BROKEN, UTS AND ANY OTHER DAMAGES G.
CHARGES. E. & O. E.	
	2019-07-17
CUSTOMER SIGNATURE	DATE