

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2019-07-05	TECHNICIAN Darren Mann		JOB/ORDER # 9493		REFERENCE TEXT Client reference
FIRST NAME David		LAST NAME Yang			
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 1803 - 938 SMITHE ST PICK UP KEYS FROM OFFICE VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.988.8470				EMAIL PMVan1@rentitfurnished.com	

REASON FOR TODAY'S CALL:

Master bathroom faucet leaking.

DESCRIPTION OF WORK PERFORMED:

The faucet was leaking from under the handle but the handle could not be removed to access the cartridge because the inside of the handle and set screw were completely rusted. I replaced the faucet with new and tested.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1	W/	Discount Labour		\$99.00	\$99.00
1	1//	Moen Danika Single Handle Lav Faucet		\$160.00	\$160.00
0	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$259.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$12.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$271.95

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON	PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY
MADE THAT SERVICES LISTED ABOVE ARE SATI	SFACTORY COMPLETED AND THAT CHARGES AND
MATERIALS LISTED HEREON ARE CORRECT. YA	LETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,
SETTLED, RUSTED, DETERIORATION, OR LEAD F	PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGE
RESULTING FROM CLEANING OR REPAIRING EX	ISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED H	HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK
CHARGES. E. & O. E.	

	2019-07-05
CUSTOMER SIGNATURE	DATE