



DATE 2019-07-26	TECHNICIAN Darren Mann	JOB/ORDER # 9545	REFERENCE TEXT Client reference
FIRST NAME Mark		LAST NAME Aceman	
BILLING ADDRESS COMPANY / BILLING NAME 337 WEST 2ND AVENUE VANCOUVER BC, V5Y1C9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 302 - 1887 CROWE ST CALL FOR ENTRY: 604.563.5068 VANCOUVER BC, BRITISH COLUMBIA, CANADA	
PHONE 604.563.5068		EMAIL mark@advancednursingcare.com	

REASON FOR TODAY'S CALL:
garburator jammed.

DESCRIPTION OF WORK PERFORMED:
The garburator grinding chamber was seized up due to rust. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$279.00
 GST (5%): \$13.95
 TOTAL: \$292.95

Mal A

2019-07-26

 CUSTOMER SIGNATURE DATE