



DATE 2019-07-30	TECHNICIAN Darren Mann	JOB/ORDER # 9554	REFERENCE TEXT Client reference
FIRST NAME Linda		LAST NAME Rainaldi	
BILLING ADDRESS COMPANY / BILLING NAME 1949 CREELMAN AVENUE VANCOUVER, V6J 1B8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1949 CREELMAN AVENUE VANCOUVER, V6J 1B8 BRITISH COLUMBIA, CANADA	
PHONE 604.723.5965		EMAIL ld.rain@telus.net	

REASON FOR TODAY'S CALL:
Garburator not working.

DESCRIPTION OF WORK PERFORMED:
I unjammed the garburator and tested by filling and draining the sink while running the garburator. Nothing was pulled out, whatever caused the garburator to seize up was pushed through and flushed away.

TECHNICIAN RECOMMENDATIONS:
I left a garburator Alan key with Linda and showed her how to use it if

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2019-07-30

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45