

Phone: 604.727.4484 yaletownplumbing.com

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2019-08-06	TECHNICIAN Darren Mann		JOB/O 9571	RDER #	REFERENCE TEXT
FIRST NAME Office		LAST NAME Admin			
BILLING ADDRESS MILLSON TECHNOLOGIES 2036 COLUMBIA ST VANCOUVER, V5Y3E1 BRITISH COLUMBIA, CANADA		\mathcal{A}	4	SERVICE ADDRESS 2036 COLUMBIA ST VANCOUVER, V5Y3E1 BRITISH COLUMBIA, CANADA	
PHONE 604.707.0414				EMAIL accounting@millson.net	

REASON FOR TODAY'S CALL:

Kitchen faucet has very low water pressure.

DESCRIPTION OF WORK PERFORMED:

The shut off valves under the sink(connected to the faucet) were breaking down internally, causing bits of rubber to clog up the faucet spray hose and head. I repaired the shut off valves by replacing the washers, stems, packing, packing nuts, and handles. I then flushed debris out of the faucet and tested. Pressure is back to normal and the shut off valves are in good working order.

QTY .	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00
1		Repair 1/2" x 3/8" Angle or Straight Stop - ADD-ON	\$25.00	\$25.00
Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$164.00	

Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.

Thank You!

ngle or Stra	aight Stop - ADD-ON	\$25.00	\$25.00	
VARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$164.00	
	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAI MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYM	GST (5%):	\$8.20	
_	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$172.20
	FROM CLEANING OR REPAIRING EXISTING FIXTURES OR CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABO			
	CUSTOMER SIGNATURE	DATE		