

HST #837181627

DATE 2019-08-15	TECHNICIAN Darren Mann		JOB/O 9583	RDER #	REFERENCE TEXT Client reference
FIRST NAME Philip		LAST NAME Cheung			
BILLING ADDRESS COMPANY / BILLING NAME 301 - 1199 SEYMOUR ST VANCOUVER, V6B1K3 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  301 - 1199 SEYMOUR ST VANCOUVER, V6B1K3 BRITISH COLUMBIA, CANADA	
PHONE 604.619.6441				EMAIL pchewebmail@gmail.com	

REASON FOR TODAY'S CALL: Garburator jammed.

Thank You!

## **DESCRIPTION OF WORK PERFORMED:**

I was able to unjam the garburator and tested by filling and draining the sink while running the garburator. During testing I noticed the kitchen sink was draining very slow. I used the PowerSpin drain snake to clean the drain and tested by filling and draining both sides of the sink. I also ran the drain snake through the lavatory drain and tested by filling and draining the sink multiple time.

QTY.	CODE		UNIT PRICE	PRICE	
1		Clean drain using PowerSp	\$159.00	\$159.00	
invoice and tell us how we did.		WARRAN	TY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$166.95
		we did.	ST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY ITHAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ITAL SERVICES AND THAT CHARGES AND ITAL SUISTED HEREON ARE CORRECT. YAI FTOWN PLIMBING IS NOT RESPONSIBLE FOR BROKEN.		

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

CUSTOMER SIGNATURE

CHARGES. E. & O. E.

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES

DATE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK