



HST #837181627

DATE 2019-08-16	TECHNICIAN Darren Mann		JOB/ORDER # 9598		REFERENCE TEXT Client reference
FIRST NAME Diane		LAST NAME Cote			
BILLING ADDRESS COMPANY / BILLING NAME 201 - 1465 COMOX ST VANCOUVER, V6G1N9 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS  201 - 1465 COMOX ST, BUZZE VANCOUVER, V6G1N9 BRITISH COLUMBIA, CANADA	
PHONE 604.682.8032				EMAIL dianecote@telus.net	

## REASON FOR TODAY'S CALL:

Pump in Toto toilet sounds like it is breathing - heavily and needs to be replaced.

## DESCRIPTION OF WORK PERFORMED:

The fillvalve wasn?t fully shutting off when the tank was full and the flapper was warping. I replaced the fillvalve, flapper, and supply line. Tested and in good working

QTY.	CODE	DESCRIPTION			PRICE
1		Replace FillValve, F	\$199.00	\$199.00	
Ruse	, 115 G	oodback	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$199.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank Youl		k page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUISTOMER SUPPLIED MATERIALS.	GST (5%):	\$9.95
				TOTAL:	\$208.95
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

2019-08-16

DATE