

HST #837181627

DATE 2019-09-13	TECHNICIAN Darren Mann		JOB/ORDER # 9647		REFERENCE TEXT Client reference
FIRST NAME David		LAST NAME Yang	97		
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 302 - 1040 PACIFIC ST KIM: 1.250.808.2545 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.988.8470				EMAIL PMVan1@rentitfurnished.com	

REASON FOR TODAY'S CALL:

Tub draining slow. Check other drains.

DESCRIPTION OF WORK PERFORMED:

-I removed hair fro the top of the tub drain and tested by filling the tub 8? and draining. -I also removed hair and gunk from the top of the lavatory drain and

QTY.	CODE			DESCRIPTION		UNIT PRICE	PRICE
1		Discount Labour	٧.,			\$99.00	\$99.00
Gwe us Feedback Please visit our feedback page at:		PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	SUBTOTAL:	\$99.00			
				GST (5%):	\$4.95		
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			TOTAL:	\$103.95			
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES A MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRU CHARGES. E. & O. E.		ONSIBLE FOR BROKEN, ND ANY OTHER DAMAGES			
			<u> </u>		2019-09-13		
				CUSTOMER SIGNATURE	DATE		