

2019-09-12

DATE

HST #837181627

DATE 2019-09-12	TECHNICIAN Darren Mann	1-01		REFERENCE TEXT Client reference
FIRST NAME Aleana		LAST NAME Mokhort		
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA				ASIDE CRESCENT 340(KEVINBPERSONAL@GMAIL.COM) IDMAXIE@GMAIL.COM
PHONE 778.980.0141	1=		EMAIL PMVan2@rentitfurn	ished.com

## REASON FOR TODAY'S CALL:

I would like to arrange the service for this unit: drain clean connection checks. Also, if you could check whether the dryer and washer each have a separate power wall socket. I understand the current machines share one power wall socket whereas the front load dryer and washer usually each requires its own power wall socket. \*no buzzer, concierge will let me up.

## DESCRIPTION OF WORK PERFORMED:

I cleaned the tub and lavatory drains and tested.

## **TECHNICIAN RECOMMENDATIONS:**

I checked behind the washer/dryer and there appears to only be one power outlet in the wall.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE			
1	116	Clean drain using PowerSpin / Tub/Shower		\$139.00			
0	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			\$139.00			
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS II	` '	\$6.95			
			TOTAL:	\$145.95			
		WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES.  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR SETTLED PUSTED DETERIORATION OR LEAD PIDES. SIXTURES OF EAN OUTS AND ANY OTHER	AND R BROKEN, ER DAMAGES				

CUSTOMER SIGNATURE