



DATE 2019-09-20	TECHNICIAN Darren Mann	JOB/ORDER # 9660	REFERENCE TEXT Client reference
FIRST NAME Karim		LAST NAME Allibhai	
BILLING ADDRESS COMPANY / BILLING NAME 4238 CARLETON AVE BURNABY, V5G3B6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 901 - 610 GRANVILLE ST, BUA#5071 MEAGAN: 604.754.9713 BURNABY, BRITISH COLUMBIA, CANADA	
PHONE 604.961.2228		EMAIL karim.allibhai@gmail.com	

REASON FOR TODAY'S CALL:
Leak under kitchen sink.

DESCRIPTION OF WORK PERFORMED:
The faucet was leaking through a crack in the spray head. I first repaired the shut off valves under the sink (connected to the faucet) by replacing the washers, stems, packing, packing nuts, and handles. I then replaced the faucet with new and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
1		Moen Banbury Faucet	\$185.00	\$185.00
2		Repair 1/2" x 3/8" Angle or Straight Stop - ADD-ON	\$25.00	\$50.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$344.00
GST (5%):	\$17.20
TOTAL:	\$361.20

_____ 2019-09-20

 CUSTOMER SIGNATURE DATE