



2019-10-01

DATE

HST #837181627

DATE 2019-10-01	TECHNICIAN Darren Mann		JOB/OF 9683	RDER#	REFERENCE TEXT Client reference	
FIRST NAME Doris		LAST NAME Mcfadyen	707			
BILLING ADDRESS COMPANY / BILLING NAME 202 - 925 WEST 8TH AVE VANCOUVER, V5Z1E4 BRITISH COLUMBIA, CANADA			(4)	SERVICE ADDRESS 202 - 925 WEST 8TH AVE, BU VANCOUVER, V5Z1E4 BRITISH COLUMBIA, CANADA		
PHONE 604.732.8420				EMAIL dorismc@shaw.ca		

REASON FOR TODAY'S CALL:

Running toilet.

DESCRIPTION OF WORK PERFORMED:

The flushvalve gasket was worn out, allowing water to slowly seep from the tank to bowl. I replaced the flushvalve gasket and tested.

QTY.	CODE		UNIT PRICE	PRICE	
1	y /	Replace FlushValve	Gasket - Kohler	\$119.00	\$119.00
<i>Q.</i>	(1	and a clay	INTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$119.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$124.95
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE